

純正対応補修用センサー参考リスト

2025年1月更新

No1

メーカー	車種	型式	年式	純正品番	補修用センサー
LEXUS	ES300h	AXZH10	2018 - 2022	42607-53020	TO06030
LEXUS	ES300h	AXZH11	2022 -	42607-53020	TO06030
LEXUS	IS500	USE30	2022 -	42607-53020	TO06030
LEXUS	LC500	URZ100	2017 -	42607-48010	TO06030
LEXUS	LC500h	GWZ100	2017 -	42607-48010	TO06030
LEXUS	LS500h	GVF50	2017 - 2020	42607-48010	TO06030
LEXUS	LS500h	GVF50	2020 -	42607-53020	TO06030
LEXUS	LS500h	GVF50	2017 - 2020	42607-48010	TO06030
LEXUS	LS500h	GVF50	2020 -	42607-53020	TO06030
LEXUS	LS500	VXFA50	2017 - 2020	42607-48010	TO06030
LEXUS	LS500	VXFA50	2020 -	42607-53020	TO06030
LEXUS	LS500	VXFA55	2017 - 2020	42607-48010	TO06030
LEXUS	LS500	VXFA55	2020 -	42607-53020	TO06030
LEXUS	LX570	URJ201W	2015 - 2021	42607-48010	TO06030
LEXUS	LX600	VJA310W	2022 -	42607-53020	TO06030
LEXUS	RC200t	ASC10	2014 2017	42607-30060	TO30060 又は TO30060L
LEXUS	RC300	ASC10	2017 - 2020	42607-30060	TO30060 又は TO30060L
LEXUS	RC300	ASC10	2021 -	42607-53020	TO06030
LEXUS	RC300h	AVC10	2014 - 2020	42607-30060	TO30060 又は TO30060L
LEXUS	RC300h	AVC10	2021 -	42607-53020	TO06030
LEXUS	RC350	GSC10	2014 - 2020	42607-30060	TO30060 又は TO30060L
LEXUS	RC350	GSC10	2021 -	42607-53020	TO06030
LEXUS	RC F	USC10	2014 - 2020	42607-30060	TO30060 又は TO30060L
LEXUS	RC F	USC10	2021 -	42607-53020	TO06030
LEXUS	RX200t	AGL25W	2015 - 2017	42607-48010	TO06030
LEXUS	RX200t	AGL20W	2015 - 2017	42607-48010	TO06030
LEXUS	RX300	AGL25W	2017 - 2022	42607-48010	TO06030
LEXUS	RX300	AGL20W	2017 - 2022	42607-48010	TO06030
LEXUS	RX450	GYL25W	2016 - 2018	42607-48010	TO06030
LEXUS	RX450	GYL25W	2019 - 2022	42607-53020	TO06030
LEXUS	RX450	GYL20W	2016 - 2018	42607-48010	TO06030
LEXUS	RX450	GYL20W	2019 - 2022	42607-53020	TO06030
LEXUS	RX450hL	GYL26W	2016 - 2018	42607-48010	TO06030
LEXUS	RX450hL	GYL26W	2019 - 2022	42607-53020	TO06030
LEXUS	RX350	TALA15	2022 -	42607-48010	TO06030
LEXUS	RX350	TALA10	2022 -	42607-48010	TO06030
LEXUS	RX450h	AALH16	2022 -	42607-48010	TO06030
LEXUS	RX450h+	AALH16	2022 -	42607-48010	TO06030
LEXUS	RX500	TALH17	2022 -	42607-48010	TO06030
LEXUS	UX200	MZAA10	2018 - 2020	42607-48010	TO06030
LEXUS	UX200	MZAA10	2020 -	42607-53020	TO06030
LEXUS	UX250h	MZAH15	2018 - 2020	42607-48010	TO06030
LEXUS	UX250h	MZAH15	2020 -	42607-53020	TO06030
LEXUS	UX250h	MZAH10	2018 - 2020	42607-48010	TO06030
LEXUS	UX250h	MZAH10	2020 -	42607-53020	TO06030
LEXUS	UX300e	KMA10	2020 -	42607-53020	TO06030
LEXUS	NX250	AAZA25	2022 -	42607-53020	TO06030
LEXUS	NX250	AAZA20	2022 -	42607-53020	TO06030
LEXUS	NX350	TAZA25	2022 -	42607-53020	TO06030

メーカー	車種	型式	年式	純正品番	補修用センサー
LEXUS	NX350 h	AAZH25	2022 -	42607-53020	TO06030
LEXUS	NX350 h	AAZH20	2022 -	42607-53020	TO06030
LEXUS	NX450 h	AAZH26	2022 -	42607-53020	TO06030
TOYOTA	Camry	AXVH70	2017 - 2024	42607-39005	TO06030
TOYOTA	Camry	AXVH75	2017 - 2024	42607-39005	TO06030
TOYOTA	Century	UWG60	2018 -	42607-06020	TO30060 又は TO30060L
TOYOTA	Crown	AZSH21	2018 - 2022	42607-59005	TO30060 又は TO30060L
TOYOTA	Crown	GWS224	2018 - 2022	42607-59005	TO30060 又は TO30060L
TOYOTA	Land Cruiser	URJ202W	2007 - 2021	42607-39005	TO06030
TOYOTA	Plado	GDJ151W	2009 - 2021	42607-39005	TO06030
TOYOTA	GR Yaris	GXPA16	2020 -	42607-19005	TO06030
TOYOTA	Mirai	JPD20	2022 -	42607-39005	TO06030
TOYOTA	bZ4X	YEAM10	2022 -	42607-02050	TO06030
TOYOTA	bZ4X	YEAM15	2022 -	42607-02050	TO06030

●製品の仕様は予告なく変更になることがあります。



ONODANI
TIRE SERVICE SOLUTION

